UNICASKET

TABLE OF WORKING PRESSURE CHANGE IN RELATION TO TEMPERATURE INCREASE ptfe tubes

°C		Usage possibilities compared to the values mentioned in the catalogues
From -60°C	to +23°C	100%
From +40°C	to +100°C	90%
From +100°C	to +150°C	55%
From +150°C	to +200°C	30%
From +200°C	to +260°C	10%